IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Corp. DATE 10/10/85 PERMIT NO. 441

PHONE: Business _____ Home _____

LOCATION 11.5 N, [illegible] on 1312, Lf on 1313, 3/4 mile & Lf on 1st Marlo Loop, Lot on Lf

SUBDIVISION NAME Carlyle Farms S. R. No. _____ LOT NO. 3 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil cl
Percolation Rate 0.5 gal/ft²/day
Topography 2-4%
Depth to Water Table 4'+
Rock or other impervious formations None Noted

Lot Area 20,000 ft²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Marlo Loop Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 246
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )
On next lot
Installed by Ed. Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: Keep well 50' minimum from all septic lines.

CERTIFICATE OF COMPLETION BY [signature] DATE 10/10/85

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White / Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold