IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Corp DATE 4-2-86 PERMIT NO. 141

PHONE: Business _____ Home _____

LOCATION 115-21N TL on 1312 (Flower House loop) TL on 1313 (Carlyle Rd) TL on To Marlo loop ~½ mile off Flower House going down Carlyle Rd S. R. No. _____


SUBDIVISION NAME Carlyle Farms LOT NO. 35 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	0.5 gal/sq ft/day	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-10%	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	~~None~~ 4'	
Lot Area 20,000 Sq Ft			Rock or other impervious formations	None obs	

(✓) Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )
Well Next door

Installed by Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY FAC

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Charles K. Barnett DATE 4-2-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink