DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Carlyle Farms 55 PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	8% ↙	0-3	scl wsbk	frssp					PS 0.3
		3-30	c mfsbk	frssp					
		30-48	cl wfsbk	frssp					
2		0-8	scl wsbk	frssp					PS 0.3
		8-48	c-cl wfsbk	frssp					
			Incl. Sa. @ 36"						
3		0-4	scl wsbk	frssp					PS 0.3
		4-40	cl wsbk	frssp					
		40-48	c wsbk	frssp					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____


21,967.50 sq. ft.
0.504 acres
N03°40'16"E
217.50'
18 CMP
56
21,967.50 sq. ft.
0.504 acres
N03°40'16"E
217.50'
LORAM DRIVE
55
24,124.41 sq. ft.
0.554 acres
N03°25'01"W
114.93'
N04°25'48"E
247.84'
54
41,644.35 sq. ft.
0.956 acres
10' FRONT MBSL
N45°23'38"W
219.61'
85' FRONT MBSL
80' FRONT MBSL
S29°35'45"W
120.31'
53
48,442.48 sq. ft.
1.112 acres
N85°42'17"W
322.77'
(8)
CRADDOCK
L11
L12
L13
L14
L15
L16
L17
C18
C19
C20
C21
C22
C23
C24