IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Copp DATE 5-22-86 PERMIT NO. 294

PHONE: Business _____ Home _____

LOCATION 21 N TL Flowerhouse loop TL on Carlyle Rd
½ mile on R Carlyle Farm Rd S. R. No. _____

SUBDIVISION NAME Carlyle Farm LOT NO. 8 SECTION OR BLOCK NO. _____


House ( ) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No ( )	Character & Porosity of Soil	Clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	4 gal/sq ft/day	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2% - 8% slp	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table		
			Rock or other impervious formations	None obs	

Lot Area 20,000 sq ft

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by F.J. Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY J.C. Moore

COMMENTS: Well has not been put down yet must be 50 from septic tank & lines

CERTIFICATE OF COMPLETION BY Charles K. Bennett DATE 5-22-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold