IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marlo Corp. DATE 10-29-85 PERMIT NO. 359

PHONE: Business _____ Home _____

LOCATION 115-21 North TL 1312 TL 1313 ~1mile TL 1st Marlo loop 5th on left

S. R. No. _____

SUBDIVISION NAME Carlyle Farms LOT NO. 6 SECTION OR BLOCK NO. _____


House ( ) Mobile Home (X) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No	(X)	Character & Porosity of Soil Clay
Auto. Dishwasher	Yes (X)	No	( )	Percolation Rate 0.5 gal/ft
Auto. Wash. Machine	Yes (X)	No	( )	Topography 2-10%
Site Suitable	Yes (X)	No	( )	Depth to Water Table 4'
				Rock or other impervious formations None obs.

Lot Area 20,000FT

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field: 3

No. of Lines _____

Sq. Ft. 120 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual (X)

Public ( )

Well on Lot 8

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: X _____

IMPROVEMENTS PERMIT BY Fred Clemmer

COMMENTS: Follow contours of hillside

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold