DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Wendy Powell
ADDRESS: 136 Clontz Hill Rd.
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): 360
LOCATION OF SITE: Same
APPLICATION DATE _____
DATE EVALUATED: 1/15/08
PROPERTY SIZE: _____
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 3%	0-6	Gr SL	vfr nsnp sapl					PS .25
		6-18	mdlk C Red	Pr 55, P, Slxp					
		18-48	mSbk/Mlk	Pr 55sp Sapl					
2	L Nearly Flat Repair	0-40	mSbk C	Pr 55 sp Sexp	Mod Sap				PS .3
		40-42	Gr L	vfr 55 Ny					
		42-48	Sand Sap Mass	vfr nsnp					
		* 30"	max depth *						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)	Gravity 25%	Pump Conv.
Site LTAR	.25	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1943): PS
EVALUATED BY: Anthony Coker
OTHER(S) PRESENT: Owner