4740993238, 192

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ostwalt Baptist Church DATE 6/23/89 PERMIT NO. 15D

PHONE: Business 192 Ostwalt Amity - Troutman Home Mance for Church -528-5310

LOCATION 21 - 115 N. TR Amity - Ostwalt Road 1st house on Right. Just before Church S. R. No.

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Character & Porosity of Soil existing

Percolation Rate


Topography

Depth to Water Table

Rock or other impervious formations

Lot Area _____

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

Size of Tank existing Gals.

Nitrification Field:

No. of Lines 4

Sq. Ft. 840 Linear Ft. 280

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Street

Installed by Edgewood Septic Tank Company

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Andre C. Pierce, R.S.

COMMENTS: Set new tank due to depth of old field

Dwelling (1st) parking

CERTIFICATE OF COMPLETION BY Andre C. Pierce, R.S. DATE 6/23/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ostwalt Baptist Church (Mance) DATE 4/27/89 PERMIT NO. _____

PHONE: Business _____ Home 528-5310

LOCATION 21 - 115 N. TR Amity - Ostwalt Rd. 1st house on R. Just before Church S. R. No. _____

SUBDIVISION NAME Mance of Church. LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil existing

Percolation Rate _____


Topography _____

Depth to Water Table _____

Rock or other impervious formations _____

Lot Area 133,515

___✓___ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank existing Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 840 Linear Ft. 280

Depth of Stone in Lines _____

Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

owell in Parking Lot.

IMPROVEMENTS PERMIT BY Andrew C. Pierce

COMMENTS: Install ~50' of Solid Sch. 40 PVC to new drainfield. Shoot Contour and keep drainlines on contour and Run them level. 18" cover over entire field.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold