DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 1
PROPERTY ID #:
COUNTY: Randall

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CARLOS CRISAFULLI APPLICANT:
ADDRESS: 4720 Hwy 82 Chain Crane APPLICATION DATE: 6/6/99 DATE EVALUATED: 6/6/99
PROPOSED FACILITY: SFR/Mobile Home PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE:
LOCATION OF SITE: Autumn Leaf Rd on Right off 21 N PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 2%	0-6	GR SL	VFR					PS .25
		6-9	SBK SCL	VFR					
		9-28	SBK CL	FR					
		28-48	ABK C	VFR					
2	L 2%	0-6	GR SL	VFR					PS .3
		6-18	SBK CCL	FR					
3	L 2%	0-7	SBK CL	FR					PS .25-.3
		7-28	SBK C	FR SS SP					
		28-32	ABK SC/SiC	FR					
		32-44	SBK CL/SiCL	FR					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	12"	Same
System Type(s)	Conv. Trench	Same
Site LTAR	.3	.25

OTHER FACTORS (.1946): B
SITE CLASSIFICATION (.1948):
EVALUATED BY: C. Hor
OTHER(S) PRESENT: Steve N.