IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Trantman Bapt. Church DATE 7-11-75 PERMIT NO. _____

PHONE: Business _____ Home Education Bldg

LOCATION Trantman – E Main St. TL on SR # 2366

S. R. No. 2366


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home ( ) Business ( ) Other Church

No. Bedrooms _____ No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No ( )	Character & Porosity of Soil	Gail
Auto. Dishwasher	Yes ( )	No ( )	Percolation Rate	2
Auto. Wash. Machine	Yes ( )	No ( )	Topography	Level
Site Suitable	Yes ( )	No ( )	Depth to Water Table	unk
			Rock or other impervious formations	Stone Bed at Inlet

Lot Area _____



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 600 Linear Ft. 240
Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (✓)

Installed by Sam Cathcart

IMPROVEMENTS PERMIT BY _____

COMMENTS: Old Septic Tank System Abandoned for Parking Area –

CERTIFICATE OF COMPLETION BY Glenn T. [illegible] DATE 7/11/75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold