SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Heritage Bldg Co. OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Jacobs Woods
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit Cu

PROFILE #	.1940 LANDSCP POSITION	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZ LTA
1	linear 6%	0to24	C SbK	S EAP	PS	PS	PS	N/A	.35
		24to48	SCL WSbK	NEAP					
2	linear 8%	0to36	C SbK	S EAP	PS	PS	PS	N/A	.32
		36to48	SCL WSbK	NEAP					
3									
4									
5									

AVAILABLE SPACE (1945): Yes SITE CLASSIFICATION (1948): PS SITE LONG-TERM ACCEPTANCE RATE: 133
EVALUATED BY: E. Moore OTHER(S) PRESENT: Rick Pappas
COMMENTS:

6190