IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Natalie Southers DATE 1-17-84 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-77 South TR on Amity Hill Rd Then TL on Murdock Rd TR on Silo Rd 300' TL on Private St. at end

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes ( )	No (✓)
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Character & Porosity of Soil Clay loam Class III
Percolation Rate .5 gal/sq. ft./day
Topography 2+8 bfo
Depth to Water Table 10'+
Rock or other impervious formations none

Lot Area 1.31 acres



Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY J. C. Moore Access Rd IP- Iron Pin

COMMENTS: well & septic system not located as shown on Improvements Permit. lines installed deep.

CERTIFICATE OF COMPLETION BY _____

EXISTING SYSTEM CHECKED BY: J. C. Moore DATE 1-17-84

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.
Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold