IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Mike Lail DATE 5-14-74 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-77 Left on Unity Hill Rd - Left on exit to I-77 Rt on Rd # 2434 1st House on Left S. R. No. 2434

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Red Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	Sandy
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Level
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	Unknown
			Rock or other impervious formations	None

Lot Area Average


EXISTING SYSTEM INSTALLED 1970

Size of Tank ✓ Gals.

Nitrification Field:
No. of Lines _____
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____

Water Supply: Individual (✓)
Public ( )

Installed by _____



Plot of System

IMPROVEMENTS PERMIT BY _____

COMMENTS: Existing Septic Tank system - No signs of surfacing

CERTIFICATE OF COMPLETION BY Glenn Fox Jr. DATE 5/14/74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold