VISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-31-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 21 Tidalmarsh PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
Pit	0-7	brn scl/cl						
	7-40	[illegible]		[illegible]				
	40-60	[illegible]		[illegible]		This pit is mostly SAPRIST with some HEMIC		PS .3 @ 30+
Pit	0-6	CL						
	6-32	1/2 [illegible]		28+				PS .3 @ 30+
	32-46	WR w/some [illegible]						
		variable soil depth following boundary						
AA	0-7	brn scl						PS .3
	7-25	SAPRIC [illegible]		[illegible]		predominately HEMIC with some SAPRIC and fibric		
	25-33	PEAT-SL SAPRIC						
	33-45	wk red scl/l						
	45-60	wk red scl/l		[illegible]				
AA	0-5	brn scl/scl						PS .3 @ 43+
	5-22	SAPRIC [illegible]						
	22-43	wk red [illegible]						
		Hit a rock @ 43" rock appears						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Usable Space (.1945)		
System Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____