DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Dixieland Tarc APPLICATION DATE ____
ADDRESS: ____
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360 gpd DATE EVALUATED: 11/25/03
LOCATION OF SITE: Lot 16 Deer Crossing ph III PROPERTY SIZE: ____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ____ PROPERTY RECORDED: ____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10% L	0-5	wfsgr B/PASSL	fri sssp					PS .25
		5-16	mfsbk RLBC	fri ss/sp ; exp					
		16-59	W fsbk YBrd	fi/fr sssp sap	comp/manx w/weathered Rock				
2	10% L	0-8	Somewhat Compacted SCR	fr sssp					PS .3
		8-20	RC SBK	fri s/sp sap					
		20-60	RCL mfsbk	fri sssp sap					
3	10% L	0-3	GR BSL	fri sssp sap					.25-.3
		3-24	mfsbk RC	fr sssp sap					
		24-67	WM fsbk YBr/Gy Cl	fr sssp Few Coarse sap					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS (Barely)
System Type(s)	9m2Sokad.	LPPBPS
Site LTAR	.25-.3	.25-.3

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DHunter, BFreeman
OTHER(S) PRESENT: ____

COMMENTS: ____