DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Dixieland Inc APPLICATION DATE: ___
ADDRESS: ___ DATE EVALUATED: 10-2-03
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 360 gpd PROPERTY SIZE: ___
LOCATION OF SITE: lot 3 Deercrossing PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	wkSBK compacted channel fi	sssp					
		9-21	wk-m fsBK RC/d	frsssp	SEXP				.3
		21-42 BC	wk fsBK L	frssp	many mi/sSAP				
		42-60	massive fsLSAP	frsssp					
			~~fine heavier~~						
2	3%	0-8	somewhat compacted channel SCL	fi-frssp					
		8-20	wk-m fsBK R heavy clay	frsssp SEXP					.3
		20-37	wk fsBK yRd/L	frsssp common mi/sSAP					
		37-46	LSAP	frsssp					
		-60	~~fine heavier~~ MfsLSAP	& frsssp					
3		0-8	wkSBK channel SCL	frssp					
		8-25	mfSBK RC	frspsexp					.3
		25-45	wk fsBK yRd L	frsssp	few mica flakes, few mi sSAP				
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	2m-25% Red.	2m 25-50% Red.
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DRH
OTHER(S) PRESENT: ___

COMMENTS: ___