4750182993

13750

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jackson E. Harwell DATE 12/19/91 PERMIT NO. 4L-3-A-25

PHONE: Business _____ Home 588-1478

LOCATION Summertree - 21N TR Oswalt Dwelly TR Franklin Woods bear (R), TR to lot on (R) of cul de sac at end of road. S. R. No. _____

SUBDIVISION NAME Summertree LOT NO. 25 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2.5

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area ~ AC

Character & Porosity of Soil P - clay - (ss)


Percolation Rate ~4

Topography ~ 20%

Depth to Water Table > 48"

Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3 @ 100' x 3'

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines _____

Water Supply: Individual (✓)

Public ( )

Installed by Ken Dellinger

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____ CUL DE SAC

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 12/19/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold