IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Martha ARTHURS. DATE 5/25/88 PERMIT NO.

PHONE: Business Home 528-4651

LOCATION: 115/21 N. TR Amity Hill Rd (1001)
TR ARTHURS RD. ON L. near end. S. R. No.

SUBDIVISION NAME LOT NO. SECTION OR BLOCK NO.


House ( ) Mobile Home (✓) Business ( ) Other

No. Bedrooms 2 No. Bathrooms ~1 1/2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clayey (sandy)
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.4gpd/ft2
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2-4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
			Rock or other impervious formations	none obs.

Lot Area ACREAGE (2 ACRES FOR THIS LOT.)

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 2
Sq. Ft. 600 Linear Ft. 200
Depth of Stone in Lines 12"
Water Supply: Individual ✓
Public ( )

Installed by CUTH BERSON

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY ACP

COMMENTS:

CERTIFICATE OF COMPLETION BY Andrew C. Price DATE 5/25/88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold