EPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
IVISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: GA Mills
DDRESS: _____ APPLICATION DATE _____
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: _____
OCATION OF SITE: Lot 25 PROPERTY SIZE: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
VALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1949 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
25-1	0-12	MA SG LS	FR NS NP	Br				
	12-24	WK SBK SL	FR SS SP	Red, Yb mix, F 10YR 7/4-3				0.25
L	24-54	WK SBK C	FR SS SP	Red/yellow, C 10YR 7/4-3				0.25
		water coming in pit on side walls @						
		36", water @ bottom of pit						
25-2	0-13	MO GR SL	FR NS NP	Br				
	13-41	WK SBK C/SC	FR SS SP	Red, C 10YR 6/6 + 7/6				0.225
L	41-56	WK SBK SCL	FR SS SP	Yel, C 10YR 6/6, F 2.5Y 7/4-3				0.25
25-3	0-10	mo gr/sbk SL	FR SS NP	Br				
	10-34	MO SBK C	FR SS SP	Red, F 10 YR 6/6				
NS	34-53	WK SBK C-C	FR SS SP	Red, Fr 10 YR 6/4-6		F SAP		0.25
	53-58	MA L SAP	FR SS SP	MULTI				
#A	0-4	Mo GR SL	FR NS/NP	Br				
AH	4-16	WK SBK SCL	FR SS/SP	Lt Red				
L	16-34	Mo SBK SC	FR SS/SP	Red; C Yel Br; F mn				0.25
	34-48	WK SBK SCL	FR SS/SP	Red; F mn				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
le Space (.1945)		
Type(s)		
R		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Karen Wallace
OTHER(S) PRESENT: _____

TS: _____

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Georgia Mills Plantation — APPLICATION DATE _____
ADDRESS: _____ — DATE EVALUATED: _____
PROPOSED FACILITY: House — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Lot 25 — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut — TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1949 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1946 RESTR HORIZ	
1	AH B L	0-24	mo SBK C	FR SS/SP	Red; F yel Br		F sap		0.3
		24-40	WK SBK SCL	FR SS/SP	multi/Red		c/m sap		
		40-48	MA SL sap	FR SS/NP	multi				
2	AH C L	0-12	mo GR SL	FR ns/np	Br				0.25
		12-24	WK SBK SCL	FR SS/SP	lt Red; F yel Br		F sap		
		24-34	mo SBK C	FR SS/SP	Red; C yel Br		C sap		
		34-48	WK SBK SCL	FR SS/SP	Rock				
3	Pit 7 L	0-25	WK SBK SCL	FR SS/SP	Red		f sap		0.3
		25-49	WK SBK C	FR SS/SP	Red		C sap		
		49-52	MA SL sap	FR SS/NP	multi; FC pockets				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Kathleen Saunders
OTHER(S) PRESENT: K Wallace

MENTS: _____