DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ___ OF ___
PROPERTY I.D.#: 46 B 57A
PROPERTY RECORDED: ___
COUNTY: ___

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: KENNETH OVERCASH OWNER: ✓ AGENT: ___ PHONE: 528-6119
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___
PROPERTY SIZE: ___
LOCATION OF SITE: ~~LOT~~ KENDALL RD. NEAR END ON ©
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other ___ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	T	0-6	GR SL	1:1 FR	P	P			
		7-17	VWSBK C	1:1 VH P S	PV	P			
		18-29	SBK/SH BS SP	1:1 /					
		30-41	~~SBK~~ GR / SL	1:1 / FF NS NP	S	P	P	S	
2									
3									
4									
5									

AVAILABLE SPACE (.1945) P SITE CLASSIFICATION (.1948): P SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: Sparks OTHER(S) PRESENT: ___
COMMENTS: Pressure Repair above MH location