Sheet ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Brian Overcash
ADDRESS: ___ APPLICANT: ___
PROPOSED FACILITY: ___ APPLICATION DATE: ___ DATE EVALUATED: 9/9/2
LOCATION OF SITE: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LL 2-4%	0-12"	Brn SCL GR						PS .3
		12"-48"	Brn/RdBrn C/L m-fSBK SS,SP,SE,FR few to many inclusions of SAP & Weathered Rock & common Mica Flakes						
2	LL 2-4%	0-5"	Brn SCL GR						PS .3
		5"-12"	Rd/Brn C/L m SBK SS,SP,SE,FR						
		12"-46"	Brn-Rd/Brn C/L m-fSBK SS,SP,SE,FR few to many SAP inclusions & weathered Rock & common Mica flakes						
		46-48"	CL SAP						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___