DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY RECORDED: _____
COUNTY: _____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Blant Arron OWNER: ✓ AGENT: PHONE: 528-9027
ADDRESS: Rt 1 Box 549 APPLICATION DATE: DATE EVALUATED: 9-1-93
Trautman PROPOSED FACILITY: Single Family Home
PROPERTY SIZE: 6.99 acres
LOCATION OF SITE: I-775 To Amity Hill TR Pilch Rd TR Pear Tree 1/2mi on rt,
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring Pit Cut

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	
1	Nose slope 3%	0 to 8"	L	Gr.	1:1	.1942 WETNES CONDITION - none
		8 to 48	C	SBK	1:1	.1943/.1956 SAPROLITE - none
						.1944 RESTRICTIVE HORIZON - None
						.1945 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .35
2	Nose slope 3 to 5%	0 to 8	L	Gr	1:1	.1942 WETNES CONDITION - None
		8 to 48	C	ABK	1:1	.1943/.1956 SAPROLITE - None
						.1944 RESTRICTIVE HORIZON - None
						.1945 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .30
3						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1945 PROFILE CLASSIFICATION -
						PROFILE LTAR -
4						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1945 PROFILE CLASSIFICATION -
						PROFILE LTAR -
5						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1945 PROFILE CLASSIFICATION -
						PROFILE LTAR -

AVAILABLE SPACE (.1945) 3/cs SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .33
OTHER FACTORS(.1946) _____ SYSTEM TYPE Conv. Gravity
EVALUATED BY: J C moore OTHER(S) PRESENT: Blant Arron
COMMENTS: _____

DRAFT