6375

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR George Mahaffey DATE 9-10-04 PERMIT NO.

PHONE: Business Home

LOCATION I-77 S TL on Amity Hill Rd TR on Pilch Rd on left past Hill-n-Dale Rd S. R. No.

SUBDIVISION NAME Hill-n-Dale LOT NO. Lt 2 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 1½

Garbage Disposal Unit Yes ( ) No ( )

Auto. Dishwasher Yes ( ) No ( )

Auto. Wash. Machine Yes ( ) No ( )

Site Suitable Yes ( ) No ( )

Lot Area 100'X200'

Character & Porosity of Soil Clay Loam


Percolation Rate 1.5 Gal/Sq. Ft./Day

Topography 2 to 4% Slope

Depth to Water Table 10'+

Rock or other impervious formations None

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System

Pilch Rd

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 720 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual ( )

Public ( )

Installed by Donald Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY D. C. Moore

The proposed / existing Sunroom 12X14 addition does not appear to impact the existing septic system.

COMMENTS: _____

**NOTE: Maintain 5' OC septic with all Sanitary Sewer Cleanouts R.S.

Maintain 5' OC Handcalls

Date: 11-9-09

ICHD-Environmental Health Division

CERTIFICATE OF COMPLETION BY D. C. Moore DATE 9-10-04

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

JAN. 1, 1989 0:05