01375

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR George Mahaffey DATE 9-10-84 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION I-77 S TL on Amity Hill Rd TR on Pilch Rd on left Past Hill-n-Dale Rd S. R. No. _____

SUBDIVISION NAME Hill-n-Dale LOT NO. 1+2 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1 1/2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil Clay Loam
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate 15 Sat/55 Unsat
Auto. Wash. Machine	Yes (✓)	No ( )	Topography 2 to 20 % Hilly
Site Suitable	Yes (✓)	No ( )	Depth to Water Table 10' +
			Rock or other impervious formations None

Lot Area 100'X200'

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Pilch Rd Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 720 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Donald Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY R. C. Moore

COMMENTS: _____

CERTIFICATE OF COMPLETION BY R. C. Moore DATE 9-10-84

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold