4751709049

09538

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Sebron Corp. DATE May 31, 1990 PERMIT NO. 4K-2-A-13

PHONE: Business _____ Home _____

LOCATION 115-21 N TR 1001 (Ostwalt - Amity Rd) TR Overcash Rd. ~ ¼ mile TL private road ~ 500' on Rt. S. R. No. _____

SUBDIVISION NAME Windbrook LOT NO. 13 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes ( ) No ( )

~~Lot Area~~ 110' x 350'

Character & Porosity of Soil slay


Percolation Rate 30

Topography 4-8% somewhat complex

Depth to Water Table 4' +

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ ~~Basement without Plumbing~~ ✓ ~~No Basement~~



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 5

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Ken Dellinger

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Sam Ingram EHS DATE 5/31/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold