00573

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Wade Henderson DATE 04-17-86 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION US 70 East, T.R. Shilo Church Rd, MHP on Rt., go to end of drive, MH on left S. R. No. _____

SUBDIVISION NAME Henderson MHP LOT NO. 27 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 15,000 ft²

Character & Porosity of Soil Clay and saprolite


Percolation Rate 0.3 gal/ft²/day

Topography 2-6% Slope

Depth to Water Table 10'+

Rock or other impervious formations None

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement




Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 800 Linear Ft. 268

Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)

Installed by Contractor

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: Step down in each line as noted above - Lines very shallow

CERTIFICATE OF COMPLETION BY Jerry L Pierce DATE 04-17-86

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold