IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR United Builders DATE 8-2-77 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION East Broad St to Sapsit Rd on Right - Go to Road # 2457 on Right - Go to RD # 2478 to left S. R. No. _____

SUBDIVISION NAME Jean Kay LOT NO. 13 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area _____

Character & Porosity of Soil Sandy Clay
Percolation Rate fast
Topography 2-6% Slope
Depth to Water Table deep
Rock or other impervious formations none



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 625 Linear Ft. 250
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Eddie Grant & Son

IMPROVEMENTS PERMIT BY Wm. Howard

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE 8/2/77

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold