35
1
105

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR J. W. Meece DATE 9/30/75 PERMIT NO. _____

PHONE Business _____ Home _____

LOCATION 526 Wilton Dr.

S. R. No. _____

SUBDIVISION NAME Del Wan LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms _____

Garbage Disposal Unit Yes ( ) No ( )

Auto. Dishwasher Yes ( ) No ( )

Auto. Wash. Machine Yes ( ) No ( )

Site Suitable Yes ( ) No ( )

Lot Area _____


Character & Porosity of Soil Clay

Percolation Rate Clay

Topography _____

Depth to Water Table _____

Rock or other impervious formations _____



Size of Tank 750 Gals.

Nitrification Field:

No. of Lines 1

Sq. Ft. 105 Linear Ft. 35

Depth of Stone in Lines 18"

Water Supply: Individual ( )

Public (✓)

Installed by Henry Sigmon

IMPROVEMENTS PERMIT BY _____

COMMENTS: Connect washer drain to septic tank system and add pit.

CERTIFICATE OF COMPLETION BY Glenn T. Cox DATE 9/30/75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold