IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System — G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Edwin Hunter Const. DATE 2-27-80 PERMIT NO. _____

PHONE Business _____ Home _____


LOCATION East Bfoat TR on St. Augusto Then TR on Glean Eagle 1/4 mion on Right S. R. No. _____

SUBDIVISION NAME Shannon acres LOT NO. 16 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2 1/2

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	Cecil Fine Sandy Clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	50 to 100 min/inch
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2 to 6%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	10'+
Lot Area	Lare		Rock or other impervious formations	Hard rock at 4½' hole to 5' depth at Tank



Plot of System

(well site not located at time of inspection)

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 16

Water Supply: Individual (✓)
Public ( )

French Drain installed above line

Installed by J. R. Bowles

IMPROVEMENTS PERMIT BY L. C. Moore

COMMENTS: Hit rock in digging Tank hole could not get deep enough for 1250' Therefore had to install special (1000 gal.) Tank manufactured by Statesville Concrete which goes in shallow. Have Tank pumped more often to compensate

CERTIFICATE OF COMPLETION BY L. C. Moore DATE 2-27-80

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold