(Continuation Sheet)

ENVIRONMENT
RESOURCES
ENVIRONMENTAL HEALTH

PROPERTY ID #:
DATE OF EVALUATION: 6-6-05
COUNTY:

Bella Terrace Lot 3

.1946 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
3	0-2							
	2-14	sbk / CL	sfi-fi / sexp	2.5YR 5/8				
	14-30	sbk / CL	fr / sexp	"				
	30-54	sbk / micaceous (c) L	vfr / sexp	2.5YR 4/6	>54	NA	>54	P 0.3
4	0-15	sbk / CL	sfi-fi / sexp	2.5YR 5/8				
	15-28	sbk / CL	fr / sexp	"				
	28-52	sbk / micaceous (c) L	vfr / sexp	2.5YR 4/6	>52	NA	>52	P 0.3
2	0-2							
	2-14	sbk / CL	sfi-fi / sexp	2.5YR 5/8				
	14-31	sbk / CL	fr / sexp	"				
	31-55	sbk / micaceous (c) L	vfr / sexp	2.5YR 4/6	>55"	NA	>55"	0.3 P

COMMENTS: Plus holes 1, 2, 4, 4S of Bill Marlin's report attached. all PS' @ 0.3

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	S	S
System Type(s)	plch	pressman; folo to plch
Site LTAR	0.3	0.3

OTHER FACTORS (.1946): Noted on System design Page 2
SITE CLASSIFICATION (.1948): P
EVALUATED BY: Andrea
OTHER(S) PRESENT: Tim Hamby

COMMENTS: