## IREDELL COUNTY HEALTH DEPARTMENT

### (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Bill Herring DATE 2/3/78 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21N, T.R. on Rd #2171 to Bayswood

S. R. No. _____

SUBDIVISION NAME Bayswood Meadows LOT NO. 32 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 3

| | | | |
|---|---|---|---|
| Garbage Disposal Unit | Yes (✓) | No ( ) | |
| Auto. Dishwasher | Yes (✓) | No ( ) | |
| Auto. Wash. Machine | Yes (✓) | No ( ) | |
| Site Suitable | Yes (✓) | No ( ) | |

Character & Porosity of Soil Lf Bz


Percolation Rate mod

Topography 2-6%

Depth to Water Table unk

Rock or other impervious formations none found

Lot Area _____




Plot of System

Size of Tank 1500 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 990 Linear Ft. 330

Depth of Stone in Lines 10"

Water Supply: Individual ( )
Public (✓)

Installed by Sigmon Septic Tank Service

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew E. Carey DATE 2/3/78

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold