DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

8764969

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

gnd 312n

OWNER: Archie Britzer APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: 1 acre 13
LOCATION OF SITE: Lot 13 Bentcreek Ph 13A PROPERTY RECORDED: 13A-20 mm
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
1	Lot 13 ~~Hole 1~~ Linear 270	0 to 48	C SbK	Fi SEAP	48 Reddish Brown	PS 48"	PS	PS	PS .28
2	Hole 2 Linear 390	0 to 36	C SbK	Fi SEAP	Reddish Brown Yellowish Brown	36" PS	PS	PS	PS .2
		36-48	C ABK	VFi SEAP					
3	Lot 13A ~~Repair lot~~	0-24"	C SbK	Fi SEAP	Red	48"	PS	PS	PS .35
		24 to 48"	C L WSbK	Fr SEAP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Gravity Pan &	Pump To panels
Site LTAR	.25	.

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: J.C. Moore
OTHER(S) PRESENT: _____