)POSED FACILITY: 3BR House PROPOSED DESIGN FLOW (.1949): 360 PROPER... 0.665 Acres
CATION OF SITE: HWY 21 N, L. Maple Creek, Lot #34 on left PROPERTY RECORDED: Yes
TER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other
ALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1955 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL CLASS & LTAR
	L 7%	0-9	w, F, sbk, scL	Fr, SS, SP, sexP					0.35
		9-24	w, F, sbk, C	Fr, SS, SP, sexP					
		24-49	w, F, sbk, Si C	Fr, SS, SP, sexP					
2	L 6.5%	0-10	w, F, sbk, SC	Fr, SS, SP, sexP					0.35
		10-30	w, F, sbk, C	Fr, SS, SP, sexP					
		30-48	w, F, sbk, Si C	Fr, SS, SP, sexP					
3	L 9%	0-8	w, F, sbk, SC	Fr, SS, SP, sexP					0.30
		8-27	w, F, sbk, C	Fr, SS, SP, sexP					
		27-48	w, F, sbk, Si C	Fr, SS, SP, sexP					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS yes	PS yes
System Type(s)	II Conv. Gravity	III 50% Reduction

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Patrick Mitchell
OTHER(S) PRESENT: LORNE COOKE

[redacted]