IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marshall Owens DATE Feb. 17, 1978 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N T.R. on S.R. 2171 to Baymont

S. R. No. _____

SUBDIVISION NAME Baymont LOT NO. 94 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 5

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area _____


Character & Porosity of Soil C f B z

Percolation Rate mpd.

Topography 2-6 %

Depth to Water Table unk.

Rock or other impervious formations none to.



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:
No. of Lines _____
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____

Water Supply: Individual ( )
Public ( )

Installed by Ronald Lackey

IMPROVEMENTS PERMIT BY A. E. Causey

COMMENTS: Septic tank replaced

CERTIFICATE OF COMPLETION BY Harold R. Hinson DATE Feb. 17, 1978

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold