314 Baymount Drive 4757-60-6363 5/1047

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Marshall Cress DATE Feb. 17, 1978 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21 N T.R. on S.R. 2171 to Baymount

S. R. No. _____

SUBDIVISION NAME Baymount LOT NO. 94 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 5

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Lot Area _____


Character & Porosity of Soil CFBz

Percolation Rate mpi.

Topography 2-6 20

Depth to Water Table ample.

Rock or other impervious formations none to.



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:
No. of Lines _____
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____

Water Supply: Individual ( )
Public ( )

Installed by Ronald Tucker

Tank is 24' from back of deck. The line from house to tank is not under the deck.

IMPROVEMENTS PERMIT BY A. E. Causey

COMMENTS: Septic tank replaced

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Feb. 17, 1978

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy

The location of the proposed screen porch addition does not appear to impact the existing septic system.
**NOTE: _____

REHS

Date: 9/26/2011

ICHD-Environmental Health Division