DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Mary Mull
APPLICANT: _____
ADDRESS: 328 Glen Cove Rd Stanley
APPLICATION DATE: 5-4-05
DATE EVALUATED: 5-6-05
PROPOSED FACILITY: _____
PROPOSED DESIGN FLOW (.1949): 100 gpd
PROPERTY SIZE: 18.75
LOCATION OF SITE: Jane Sowers Rd (FL) Belmont (D) Belmont Bypass (T) Burton Plant - end
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 7% | 0-6 | L WSBL | Fr SS SP Sap | | 18 | | | PS .3 |
| | | 6-40 | C SBL | Fr SS SP Sap | | | | | |
| | | 40-48 | C/Sap WSBK | Fr SS SP Sap | | | | | |
| 2 | 7% | 0-9 | C WSBL | Fr SS SP Sap | | 48 | | | PS .3 |
| | | 9-39 | C SBK | Fr SS SP Sap | | | | | |
| | | 39-48 | C/Sap WSBL | Fr SS SP Sap | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | 334 / 112 | 334 / 112 |
| System Type(s) | Conventional | Conventional |
| Site LTAR | .3 | .3 |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Kelly Cook
OTHER(S) PRESENT: _____