IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ronald Bennett DATE 6 Mar 75 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 21 N to Hebron Ch Rd (SR 1919) on left go to 1st house on Right past Mt. Sinai Church. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 1

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes ( ) No (✓)
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil Red Clay
Percolation Rate none
Topography Slight Slope to left of house
Depth to Water Table ok
Rock or other impervious formations ok

Lot Area _____



Plot of System

Size of Tank Regan Gals.
Nitrification Field:
No. of Lines 1
Sq. Ft. 250 Linear Ft. 100
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by Ray Lentz

IMPROVEMENTS PERMIT BY _____

COMMENTS: 27½" rise over the dam - 2¼" fall in drain line all line was high - had very little fall from tank to line stub-out here and tank deep. all line open - Tank had been pumped

CERTIFICATE OF COMPLETION BY WM Howard DATE 6 Mar 75

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold