DEPARTMENT OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Joel Howard
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: 2/18/92
LOCATION OF SITE: Country View Estates Lot #4 PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

141
-92
49

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	L 5-6%	0-22"	Rd/Brn SBK	M/CL, S, PSE, FI-FR	WSBK FR				PS .275 .3
		22-48"	Rd/Brn	CL, SS, SP, SE					
			w/ Common Mica Flakes &	SAP & Weathered Rock Inclus					
2	L 5-7%	0-24"	Rd/Brn SBK	M/CL, S, PSE, FI-FR					PS .3
		24-48"	Rd/Brn SBK	CL, SS, SP SE	FR w/ Common Mica				
			Flakes, SAP & Weathered Rock Inclus						
3	L 5% Repair Area	0-24	Rd/Brn SBK	C/CL, S, P, SE, FI					PS .25
		24-48	Rd/Brn	C/CL, WSBK, SS, SP SE, FI-FR					
			w/ Inclus of SAP & Hard Weathered Rock						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____