ON OF ENVIRONMENTAL HEALTH
E WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## for ON-SITE WASTEWATER SYSTEM

Mark Johnson

ER: Joe Ervin APPLICANT: _____

DRESS: 251 John's Pond Ln APPLICATION DATE: _____ DATE EVALUATED: 2-12-03

OPOSED FACILITY: 2 PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

CATION OF SITE: _____ PROPERTY RECORDED: _____

TER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| Initial | 0-10" | Brw L/SL wSBK | GR, SS, SP, SE, FR w/ Common Mica Flakes | | | | | PS .25 |
| | 10-48 | Brw (Mott) L/SL wSBK | GR, SS, SP, SE, FR w/ Common Mica Flakes & few to many SAP Inclus | | | | | |
| Initial | 0-6" | Brw, SCL | GR, FR | | | | | PS .25 to 32" |
| | 6"-32" | Rd/Brw to Brw L/SL | SS, SP, SE, FR w/ Common Mica Flakes | Dk mwSBK Heavy w/ lots of SAP Inclus | | | | |
| | 32-42" | L/SL | Brw SAP | | | | | |
| Repair Slope above Bldg | 0-8 | DK Brw SCL/L | | (Top Soil) | | | | PS .2 to .25 |
| | 8-34" | Rd/Brw Cl mwSBK | SS, SP, SE, FR w/ few to many SAP Inclus, Small Pieces of Rock | | | | | |
| | 35" | Hard SAP or w | Rock (couldn't Auger thru) | | | | | 34" |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| uilable Space (.1945) | | |
| tem Type(s) | | |
| LTAR | | |

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____

OTHER(S) PRESENT: _____