DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Larry Howard — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 1/9/98
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: _____ — PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | 1940 LAND-SCAPE POSITION/ SLOPE % | HORI-ZON DEPTH (IN.) | SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE | 1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR | 1943 SOIL DEPTH | 1956 SAPRO CLASS | 1944 RESTR. HORIZ. | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | LL 4-5% | 0-24 | Rd/Brn C SBK S-SS, P-SP | Se, Fi-FR | | | | | |
| | | 24-36 | Rd/Brn Cl SBK SS, SP, Se, Fi-FR w/ Inclus of SAPS | | | | | Weathered Rock | PS .275, 3 to 36" |
| | | 36" | Weathered Rock — Could not Auger any further | | | | | | |
| 2 | LL 4-5% | 0-18" | Rd/Brn SBK C SSS, P-SP | Se, Fi-FR | | | | | PS .3 |
| | | 18"-48" | Rd/Brn Cl SBK SS-S | SP, Se, FR | | | | | |
| | | | w/ Inclus of Rock Fragments | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____




NORTH CAROLINA REGISTERED SEAL ★ L-1408 LAND SURVEYOR ROBERT J. LACKEY

ROBERT J. LACKEY

I, ~~L. B. GRIER~~, REGISTERED LAND SURVEYOR CERTIFY THAT THIS MAP WAS DRAWN FROM AN ACTUAL FIELD SURVEY PERFORMED UNDER MY DIRECTION AND SUPERVISION. THAT THE RATIO OF PRECISION IS _____ AND THAT THIS MAP CONFORMS TO GS47-30 AS AMENDED.

WITNESS MY HAND AND SEAL THIS 16 DAY OF February, 1984

REGISTERED LAND SURVEYOR

L-1408