DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Roger Corcoran APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 5-30-03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 19 phs 2 Shamrock Est PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut Now Lot 18
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2-4% L	0-10	wk fsbk brn-rbrn scl	fr sss p					.25
		10-47	wk-m fsbk R C	fr sp sep few g w rock near bottom of pit					
2		0-5	wk sbk brn sl/scl	fr sss p					.3 ≤ 29"
		5-14	wk fsbk brn w/ rbrn c	fr sp sep					
		14-29	m-m abk R cl	fr sss p sep					
		29-50	wk fsbk R cl	fr sss p common-many g w. Rock					
3		0-7	gr-wk sbk brn scl	fr sss p					.25 ≤ 30" 25" max 46
		7-30	wk-m fsbk/abk R	fr sp sep					
		30-50	wk-m abk R cl	fr sss p few common g w. rock water seeping into pit ~37"					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	45	45
System Type(s)	Pln Conv	Pln Conv.
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): B3
EVALUATED BY: DPH
OTHER(S) PRESENT: _____

COMMENTS: _____

S02°01'59"E
110.00'
105.00'
New Lot 18
19
18
17
30,291.58 sq.ft.
0.695 acre
31,009.13 sq.ft.
0.712 acre
30,758.49 sq.ft.
0.706 acre
30,250.00 sq.ft.
0.694 acre
N87°58'01"E
275.00'
276.97'
287.49'
298.38'
35' FRONT
MBSL
46.54'
C1
C2
68.07'
105.56'
N03°53'19"E
110.00'
N02°01'59"W
CMP
S03°53'19"W
53.64'
110.00'
S02°01'59"E
110.59'
66.13'
C10
C11
31
32
260.00'
600.00 sq.ft.
0.657 acre