4760979594

08979

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Roland Estep DATE Sept. 21, '88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115 N TR 2383 (Shinnsville Rd.) x Creek & 1 mile TR on private road (dirt) near end on Rt. S. R. No. _____

SUBDIVISION NAME J. Bowles Prop. (Former Tolbert Estate) LOT NO. 17 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes ( )	No (✓)	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site ~~Suitable~~ RS	Yes (✓)	No ( )	

Lot Area 20000+ sq ft

Character & Porosity of Soil clay


Percolation Rate 2, 4

Topography 2% 4%

Depth to Water Table _____

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 600 Linear Ft. 200

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Tim Smith
Cedarwood Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY _____ DATE Sept 21, '88

SEPTIC SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making this Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

08979

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Roland Estep DATE Sept 13, 88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 2383 (Shinnville Rd.) X Creek on 1 mile TL private (acess) road on Rt. S. R. No. _____

SUBDIVISION NAME J.R. Bowles prop (formerly Tolbert Estate) LOT NO. 17 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable ~~YS~~ Yes (✓) No ( )

Lot Area 20000 ft²+

Character & Porosity of Soil shallow clay


Percolation Rate n.t.

Topography 2% 4+

Depth to Water Table _____

Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 600 Linear Ft. 200

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: X Roland E. Estep

IMPROVEMENTS PERMIT BY David R. Hinson, RS.

COMMENTS: Follow contour with drainfield, install drainfield at a depth of 24" to trench bottom (12" cover).

IFICATE OF COMPLETION BY _____ DATE _____

NG SYSTEM CHECKED BY: _____ DATE _____

ONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making ents Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold