IREDELL COUNTY HEALTH DEPARTMENT

07733

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR David Stikeleather DATE Nov. 3, '89 PERMIT NO. 4J-A-46

PHONE: Business _____ Home _____

LOCATION 115-21 N. TR 2383 (Shinnville Rd.) x Creek ~1/2 miles on left S. R. No. _____


SUBDIVISION NAME Former Tolbert Est. - Stikeleather Dev. LOT NO. 5 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2
Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ RS Yes ( ) No ( )
Lot Area ~1/2 AC

Character & Porosity of Soil clay
Percolation Rate 2-4
Topography 6-8%
Depth to Water Table 4'+
Rock or other impervious formations none obs.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. ~~300~~
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Curtis Peterson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY [signature]

COMMENTS: _____

CERTIFICATE OF COMPLETION BY [signature], RS. DATE 11-3-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

Access Road 2383 - ↓

07733

24:30

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR David Stikeleather DATE Dec 8, '87 PERMIT NO. _____

PHONE: Business 878-6619 Home _____

LOCATION 115-21 N. TR 2383 (Shinnville Rd) x Creek ~1½ miles on left

SUBDIVISION NAME Former Tolbert Estate Stikeleather Subdivision LOT NO. 5 S. R. No. _____ SECTION OR BLOCK NO. _____


House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	~1	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	6-8%	
Site Suitable	Yes ( )	No ( )	Depth to Water Table	4'	
			Rock or other impervious formations	none obs.	

Lot Area ~½ AC

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

50' to well site

Signed: X D. D. Stikeleather

IMPROVEMENTS PERMIT BY David R. Hinson, R.S.

COMMENTS: Follow contour with drainfield. Use drop boxes to distribute effluent. Install drainfield no deeper than 30" to bottom of ditch.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold