# SOIL/SITE EVALUATION

*(Continuation Sheet)*

*Sheet ____ of ____*

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #: _____
DATE OF EVALUATION: _____
COUNTY: _____

Oak Ridge Lot 24

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| B | SS | 0-6 | B SCL Gr | SS,SP,Fr SE,P | — | 48" | — | — | PS |
| 24A | 10-15% | 6-29 | R C/CL WFSBk | SS,SP,Fr SE,P | Common Sap | | | | |
| | | 29-48 | R CL UWFSBk | SS,SP,Fr SE,P | many Sap | | | | .3 |
| | | | | | | | | | |
| | | | | | | | | | |
| B | SS | 0-6 | B SCL Gr | SS,SP,Fr SE,P | — | 40" | PS | — | PS |
| 24B | 10-15% | 6-26 | R C WFSBk | SS,SP,Fr SE,P | | | | | |
| | | 26-40 | R CL WFSBk | SS,SP,Fr SE,P | Common Sap | | | | |
| | | 40-48 | V.F. SL Sap Mass | SS,SP,Fr SE,P | few common RC incl. | | | | .3 |
| | | | | | | | | | |
| D | SS | 0-30 | RB C UWSBk | SS,P,Fi-Fr SE,P | few/common WK/sap incl | 30" | PS | — | PS |
| 24C | 5-10% | 30-48 | RB SL Sap Mass | SS,SP,Fr SE,P | few RC incl. | | | | .275<30" |
| | | | | | | | | | .35>30" |
| | | | | | | | | | |
| | | | | | | | | | |
| B | SS | 0-15 | RB C UWSBk/UWSBk | SS,P,Fi-Fr SE,P | — | 48" | — | — | PS |
| 24D | 10-15% | 15-48 | R CL WFSBk | SS,SP,Fr SE,P | Common Sap | | | | |
| | | | | | | | | | .3 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

COMMENTS: _____

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: Corinthian Builders — APPLICATION DATE 1/3/07
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Oak Ridge #24 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-6" | Brn to Rd/Brn SCL | | | | | | PS .3+ |
| | | 6"-24" | Rd/Brn | C/CL m-wSBK | | | | | |
| | | 24-42 | Rd/Brn | CL-wSBK | wf a to many S/P Indicts | | | | |
| | | 42"-48" | L/SL | S/P | | | | | |
| 2 | | | | | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____