SOIL/SITE EVALUATION

(Continuation Sheet)

Sheet 3 of 3

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #: ______
DATE OF EVALUATION: ______
COUNTY: ______

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
P 4	LS 4%	0-9	FILL		Comm. Dr. Mott	54"			PS .25
		9-13	YBr. SCL WSBK	FR SS/SP					
		13-38	R Clay ABK	FR SS/SP					
		38-54	R CL WSBK	FR SS/SP					

COMMENTS: Please note all of the pits exhibit a small amount of compaction at the surface due to a spoil pile that was located on the lot. MA&Assoc., Inc. recommends that this system's trench bottom be located at 36" in order to take advantage of better soil conditions, our LTAR reflects this.