ON-SITE WASTEWATER SECTION COUNTY

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Rufus Hargrove OWNER AGENT PHONE
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY: Single Family Dwelling
PROPERTY SIZE:

LOCATION OF SITE: 105 Glassy Rd
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit Cut

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	
1	Linear 6%	0-4/4	L	GR		.1942 WETNESS CONDITION - N/A
		4-48	C	ABK	1:1	.1943/.1955 SAPROLITE - N/A
						.1944 RESTRICTIVE HORIZON - N/A
						.1948 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .3
2	Linear 6%	0-4/4	L	GR		.1942 WETNESS CONDITION - N/A
		4-48"	C	ABK	1:1	.1943/.1955 SAPROLITE - N/A
						.1944 RESTRICTIVE HORIZON - N/A
						.1948 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .3
3						.1942 WETNESS CONDITION -
						.1943/.1955 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
4						.1942 WETNESS CONDITION -
						.1943/.1955 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
5						.1942 WETNESS CONDITION -
						.1943/.1955 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -

AVAILABLE SPACE (.1945) Yes SITE CLASSIFICATION (.1948): ~~PS~~ NA SITE LONG-TERM ACCEPTANCE RATE: .3
OTHER FACTORS(.1946) SYSTEM TYPE Conv. Gravity
EVALUATED BY: OTHER(S) PRESENT: Rufus Hargrove
COMMENTS:

DRAFT

000615