IREDELL COUNTY HEALTH DEPARTMENT

12595 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Dale Tolbert DATE 3/26/91 PERMIT NO. SB-A-48

PHONE: Business _____ Home 872-8060

LOCATION Brawley Rd (SR 2382), last house on (L) before Oswalt Amity Rd intersection

S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Clay - sol
Percolation Rate .4
Topography 2-3%
Depth to Water Table 48"
Rock or other impervious formations None found

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System Brawley Rd

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3 @ 100
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )
D/W next door at parents house
Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: Thelma Tolbert

IMPROVEMENTS PERMIT BY Wesley Sparks R.S.

COMMENTS: Keep trenches shallow - no deeper than 36" to trench bottom. Lines must follow slope in direction shown on this sketch. Conventional trenches may be used.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold