OF ENVIRONMENTAL HEALTH:
WASTEWATER SECTION

2-4-2008 Site has been cut per Joe Lynn / Russell Williams (1-2') option – Laterals to be installed At 36" +/-

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 2-3-2008
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 20 Deer Valley PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ bedrock ~56" (4) Depth Limitation?
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut looks like Need more Tobacco 3rd pass
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Pit 5 2-Tip bwsal dk 2 ~23" 7-12 ybrn c frsp mxed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-14	g brn sdl		~22"				(4)
		14-28	wk sbk rC common y-brn mottles few ch 2						
		28-48	wk sbk gyrsdl/sl fr sssp		looks PS	28-48"			
2		0-6	g brn sdl		17"~36"				(4)
		6-34	wk sbk rC common f-d brn mottles few ch 2 f-sl sssp						
		34-48	wk sbk gyr sdl/sl fr sssp		looks like it might be PS	>36"			
3	See lot 19 notes	0-12							.25
		12-48							
4		0-7	g brn sdl fr sssp mxed		29-48"				.05-.1 LPP
		7-29	wk sbk pbrn, y-brn c						
		29-48	gleyed c f-sl sp						
		48-60+	L sap fr sssp						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____