VISION OF ENVIRONMENTAL HEALTH:
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-8-99
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Lot 50 Deer Valley PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Dig pits deeper #'s 2+3 w/ good bkgr to 36"+6 depth

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-12	Comm sc/c	fr					PS .3-.25
		12-22	w/ few rdsh mott	fr ss sp					
		22-36	BW/Mott 2C common	mod sp fr sp					
		36-60	L-fsl	sp fr sp		gets darker w/ depth			
		0-10	brn sl fine	ss sp					PS .3
		10-32	BW/Mott rdsh c/c	fr ss sp	common y-brn mott 16"				
		32-42	BC W/Mott 2C	common mod sp fr sp					
		42-53+	mott	common mod sp	fr ss sp-wp				
10-29-99		53-60+	L sap	fr ss sp	looks good				54+
		0-6	brn sil	fr					probably PS .3
		6-28	Subsoil c/c	fr sp ss sp					
		28-43	BC W/Mott RDsh/c	common mod sp	fr ss sp-wp				
		43-57	L sap - L	common mod sp	fr ss sp-wp				
10-29-99		57-65	L sap	fr sap	looks good				54+

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
uitable Space (.1945)		
em Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____