VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: Danny Safrit APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/3/2011
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Brawley Rd PROPERTY RECORDED: _____
ATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
'ALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
~15' behind House	0-4	Brw SiL	GR FR					PS .31
	4-22	Rd/Brw C	m SBK S-SS, P-SP, SE, FI					
	22-34	Rd/Brw C	m-w SBK S-SS, SP, SE, FR w/ Few to many SAP Inclus			Common Mica Flakes		
	34-48"	L-SL	SAP					
Rt of House Looking N 60'+	0-12"	Yel/Brw C	S, P, SE, FI					Unsat 25"
	12-24"	Red/Brw C	S, P, SE-E, FI					
To Rt of MH & next to XO +	0-6"	Brw SiL	GR FR					PS .3 to 30"
	6-30"	Red/Brw C	m-w SBK S-SS, SP, SE, FI-FR w/ Few to many SAP Inclus			Common Mica Flakes		
	30-48"	L/SL	SAP					
Last line of Initial System	0-6	Brw SiL	GR FR					PS .3
	6-34	Rd/Brw C	m SBK S-SS, SP, SE, FI-FR, Common Mica w/ Few to many SAP Inclus					
	34-40	Rd/Brw C	m-w SBK S-SS, SP, SE, FR					
	41	SAP						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____