VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 12-9-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 21 continued Dr. Whitley PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
5	0-11	gr-wk sab pbrk	sl fr					
	11-36	m-wk sab RC	fi sp few common y brn mottles					.2-.25
	36-50	wk fsab RCh	few mdsmp fr ssp					.3
	50-60	LSmp	fr ss sp					.4
				gray below layer at maybe 40-48 inches				
6	0-5	gr-wk sab brn sl	fr					
	5-21	sab rc	fi sp few brn mottles few in sp					.25
	21-36	wk fsab red	few-common in sp fr ss sp					.3
	36-60	wk fsab	L/fin s L sm sp fr ss sp					.4

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		
: LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

VISION OF ENVIRONMENTAL HEALTH:
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

WNER: _____ APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 10-6-99
ROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
OCATION OF SITE: Lot 21 Deer Valley PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed Big area fill

	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-5	brn sl fr						PS .9
		5-16	SAB e-c/cl fr ss-sp						
		16-33	f SAB fr ss-sp						
		33-62	fine sL sap fr ss sp f sand gravsap						
		0-22	brn sicl fr ss-sp						
		22-41	yR c/cl fi sp ss-sp		g brn mottles, few ch 2-5				
		41-60	e LP/sap fr ss-sp-gravs		Looks like this type of				
12-9-99		0-8	g brn sl/scl fr						PS .3
		8-18	SAB RC fi sp						
		18-45	(B-C) w/f SAB RCL fr ss ss sp few		wil sap - increasing w/ depth				
		45-59	LSAP fr ss sp.						
		0-11	gn brn scl fr						LP soil depth only .1-.1.5
		11-39	SAB y-brn, gy c/cl fr sp	common	32-40" y brn mottles, few ch 2- 32-40"				
		39-54	w/f SAB RCL fg-sp ss sp		common y brn at upper part of horizon - appear to diminish w/ depth				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
stem Type(s)		
e LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____